



# BOSCH

Разработано для жизни



1	2	3	4	5
1607031255	1607031250	1607031266	1607031256	1607031223
6	7	8	9	10
1607031227	1607031252	1607031260	1607031254	1607031236
11	12	13	14	15
1607031264	1607031265	1607031263	1607031259	1607031222

Перфоратор (GBH)		Отбойный молоток (GSH)		Угловая шлифмашина (GWS)	
<b>GBH 11 DE</b>	0 611 245 703, 708	<b>GSB 20-2 RET</b>	0 601 19B 903	<b>GWS 1000</b>	3 601 H21 003, 8R0
<b>GBH 2-22 E</b>	0 611 250 603, 608	<b>GSB 20-2 RET</b>	0 601 192 803, 868, 880, 890	<b>GWS 1000</b>	3 601 H28 400, 800
<b>GBH 2-22 RE</b>	0 611 250 708	<b>GSB 21-2 RCT</b>	3 601 A9C 700, 701	<b>GWS 10-125</b>	3 601 H21 000, 020, 800
<b>GBH 2-22 S</b>	0 611 250 003	<b>GSB 21-2 RE</b>	3 601 A9C 500, 501, 600, 601	<b>GWS 10-125 C</b>	0 601 802 703, 903
<b>GBH 2-23 RE</b>	3 611 B50 400	<b>GSB 450 RE</b>	0 601 149 703, 708	<b>GWS 10-125 C</b>	0 601 702 703, 708, 773, 903
<b>GBH 2-23 REA</b>	3 611 B50 500	<b>GSB 680 PROFI</b>	0 601 184 351	<b>GWS 10-125 C</b>	0 601 802 503, 508
<b>GBH 2-24 DFR</b>	3 611 B73 000	<b>GSB 780-2 RE</b>	3 601 A7B 101	<b>GWS 10-125 CE</b>	0 601 383 703
<b>GBH 2-24D</b>	3 611 BA0 000	<b>GSB 13</b>	3 601 B17 092	<b>GWS 10-125 CE</b>	3 611 C21 000
<b>GBH 2-24DF</b>	3 611 BA0 100	<b>GSB 13 RE</b>	3 601 B17 100, 101, 102, 105, 106, 107	<b>GWS 10-125 CE</b>	0 611 318 703, 708
<b>GBH 2-25 DV</b>	3 611 B67 103	<b>Отбойный молоток (GSH)</b>		<b>GWS 10-125 Z</b>	3 601 H32 000
<b>GBH 2-26 DBR</b>	0 611 255 503	<b>GSH 11 E</b>	0 611 316 703, 708, 796	<b>GWS 10-125C</b>	0 601 802 573, 574, 703, 708, 773
<b>GBH 2-26 DFR</b>	0 611 254 703, 708	<b>GSH 16-28</b>	3 611 C35 000	<b>GWS 10-125CE</b>	0 601 803 773
<b>GBH 2-26 DRE</b>	0 611 253 703, 708	<b>GSH 16-30</b>	3 611 C35 100	<b>GWS 11-125</b>	3 601 G92 000, 0R0
<b>GBH 2-26 E</b>	0 611 251 603	<b>GSH 5 CE</b>	3 611 C21 000	<b>GWS 11-125</b>	3 601 G9D 000
<b>GBH 2-26 RE</b>	0 611 251 703, 708	<b>GSH 5 E</b>	0 611 318 703, 708	<b>GWS 11-125 CI</b>	3 601 H22 000, 020
<b>GBH 2-28</b>	3 611 B67 500	<b>Угловая шлифмашина (GWS)</b>		<b>GWS 11-125 CIE</b>	3 601 H23 000, 020
<b>GBH 2-28 F</b>	3 611 B67 600	<b>GWS 1000</b>	3 601 H21 003, 8R0	<b>GWS 11-125 CIH</b>	3 601 H30 100, 120, B00
<b>GBH 2400</b>	0 611 253 803	<b>GWS 1000</b>	3 601 H28 400, 800	<b>GWS 11-125 P</b>	3 601 G92 200
<b>GBH 2600</b>	0 611 254 803	<b>GWS 10-125</b>	3 601 H21 000, 020, 800	<b>GWS 12-125</b>	3 601 G93 000
<b>GBH 3-28 DFR</b>	3 611 B4A 000	<b>GWS 10-125 C</b>	0 601 802 703, 903	<b>GWS 12-125 CIE</b>	3 601 G94 000
<b>GBH 3-28 DRE</b>	3 611 B3A 000	<b>GWS 10-125 C</b>	0 601 702 703, 708, 773, 903	<b>GWS 12-125 CIEP</b>	3 601 G94 200
<b>GBH 5-40 DCE</b>	3 611 B64 000, 001	<b>GWS 10-125 C</b>	0 601 802 503, 508	<b>GWS 12-125 CIEPX</b>	3 601 G94 300
<b>GBH 5-40 DE</b>	0 611 241 703, 708	<b>GWS 10-125 CE</b>	0 601 383 703	<b>GWS 12-125 CIEX</b>	3 601 G94 100
<b>GBH 7 DE</b>	0 611 235 703, 708	<b>GWS 10-125 CE</b>	0 601 703 703, 708, 773	<b>GWS 12-125 CIP</b>	3 601 G93 200
<b>GBH 7-45 DE</b>	0 611 235 803, 808	<b>GWS 10-125 CE</b>	0 601 703 903	<b>GWS 12-125 CIPX</b>	3 601 G93 300
<b>GBH 7-46 DE</b>	0 611 263 703, 708	<b>GWS 10-125 CE</b>	0 601 803 503, 508, 573, 574, 575, 703, 708	<b>GWS 12-125 CIX</b>	3 601 G93 100
<b>Шлифмашина по бетону (GBR)</b>		<b>GWS 10-125 Z</b>	3 601 H32 000	<b>GWS 13-125 CI</b>	3 601 G93 0R0
<b>GBR 15 CA</b>	3 601 G76 000	<b>GWS 10-125C</b>	0 601 802 573, 574, 703, 708, 773	<b>GWS 13-125 CI</b>	3 601 G9E 000
<b>Эксцентриксовая шлифмашина (GEX)</b>		<b>GWS 10-125CE</b>	0 601 803 773	<b>GWS 13-125 CIE</b>	3 601 G94 0R0
<b>GEX 150 TURBO</b>	0 601 250 703, 772, 791	<b>GWS 11-125</b>	3 601 G92 000, 0R0	<b>GWS 13-125 CIE</b>	3 601 G9F 000
<b>Прямая шлифмашина (GGS)</b>		<b>GWS 11-125</b>	3 601 G9D 000	<b>GWS 13-125 CIEX</b>	3 601 G9F 100
<b>GGS 28 C</b>	3 601 B20 000	<b>GWS 11-125 CI</b>	3 601 H22 000, 020	<b>GWS 13-125 CIEX</b>	3 601 G9E 100
<b>GGS 28 CE</b>	3 601 B20 100	<b>GWS 11-125 CIE</b>	3 601 H23 000, 020	<b>GWS 1400</b>	3 601 H24 800, 830, 8R0
<b>GGS 28 LC</b>	3 601 B21 000	<b>GWS 11-125 CIH</b>	3 601 H30 100, 120, B00	<b>GWS 14-125 C</b>	0 601 704 703, 708, 903
<b>GGS 28 LCE</b>	3 601 B21 100	<b>GWS 11-125 P</b>	3 601 G92 200	<b>GWS 14-125 CE</b>	0 601 705 703, 708
<b>GGS 28 LP</b>	3 601 B25 000	<b>GWS 12-125</b>	3 601 G93 000	<b>GWS 14-125 CI</b>	3 601 H24 000, 020
<b>GGS 8 CE</b>	3 601 B22 100	<b>GWS 12-125 CIE</b>	3 601 G94 000	<b>GWS 14-125 CIE</b>	3 601 H25 000, 020
<b>Дисковая циркулярная пила (GKS)</b>		<b>GWS 12-125 CIEP</b>	3 601 G94 200	<b>GWS 14-125 CIT</b>	3 601 H29 000, 020, A00, A30
<b>GKS 160</b>	3 601 F70 000, 002	<b>GWS 12-125 CIEPX</b>	3 601 G94 300	<b>GWS 14-125 INOX</b>	3 601 H29 J00
<b>GKS 55</b>	3 601 F64 000	<b>GWS 12-125 CIEX</b>	3 601 G94 100	<b>GWS 14-125C</b>	0 601 804 503, 508, 573, 574, 703, 708, 773
<b>GKS 55</b>	3 601 F64 001	<b>GWS 12-125 CIP</b>	3 601 G93 200	<b>GWS 14-125CE</b>	0 601 805 503, 508, 573, 574, 703, 708, 773
<b>Штроборез (GNF)</b>		<b>GWS 12-125 CIPX</b>	3 601 G93 300	<b>GWS 14-150 C</b>	0 601 706 703
<b>GNF 65 A</b>	0 601 368 703, 708	<b>GWS 12-125 CIX</b>	3 601 G93 100	<b>GWS 14-150 CI</b>	3 601 H26 000, 020
<b>GNF 35 CA</b>	0 601 621 703, 708	<b>GWS 13-125 CI</b>	3 601 G93 0R0	<b>GWS 14-150C</b>	0 601 806 503, 573, 574
<b>Универсальный резак (GOP)</b>		<b>GWS 13-125 CI</b>	3 601 G9E 000	<b>GWS 14-150C</b>	0 601 806 703, 708, 732, 773
<b>GOP 2000 CE</b>	3 601 B30 001	<b>GWS 13-125 CIE</b>	3 601 G94 0R0		
<b>GOP 250 CE</b>	3 601 B30 000	<b>GWS 13-125 CIE</b>	3 601 G9F 000		
<b>GOP 30-28</b>	3 601 B37 000	<b>GWS 13-125 CIEX</b>	3 601 G9F 100		
<b>Поліровальная машина (GPO)</b>		<b>GWS 13-125 CIEX</b>	3 601 G9E 100		
<b>GPO 14 CE</b>	3 601 C89 000	<b>GWS 1400</b>	3 601 H24 800, 830, 8R0		
<b>Ударная дрель (GSB)</b>		<b>GWS 14-125 C</b>	0 601 704 703, 708, 903		
<b>GSB 16 RE</b>	3 601 A4E 500, 530, 600	<b>GWS 14-125 CE</b>	0 601 705 703, 708		
<b>GSB 18</b>	0 601 195 003	<b>GWS 14-125 CI</b>	3 601 H24 000, 020		
<b>GSB 18 RE</b>	0 601 195 703	<b>GWS 14-125 CIE</b>	3 601 H25 000, 020		
<b>GSB 18-2</b>	0 601 185 003	<b>GWS 14-125 CIT</b>	3 601 H29 000, 020, A00, A30		
<b>GSB 18-2 E</b>	0 601 180 703	<b>GWS 14-125 INOX</b>	3 601 H29 J00		
<b>GSB 18-2 E</b>	0 601 185 703	<b>GWS 14-125C</b>	0 601 804 503, 508, 573, 574, 703, 708, 773		
<b>GSB 18-2 RE</b>	3 601 AA2 200	<b>GWS 14-125CE</b>	0 601 805 503, 508, 573, 574, 703, 708, 773		
<b>GSB 18-2 RE</b>	0 601 185 503	<b>GWS 14-150 C</b>	0 601 706 703		
<b>GSB 19-2 RE</b>	3 601 A7B 500, 600	<b>GWS 14-150 CI</b>	3 601 H26 000, 020		
<b>GSB 19-2 REA</b>	3 601 A7C 500	<b>GWS 14-150C</b>	0 601 806 503, 573, 574		
<b>GSB 20-2</b>	0 601 19B 003	<b>GWS 14-150C</b>	0 601 806 703, 708, 732, 773		
<b>GSB 20-2</b>	0 601 184 003				
<b>GSB 20-2 RCE</b>	0 601 19B 703				
<b>GSB 20-2 RCE</b>	0 601 192 703, 708, 770				
<b>GSB 20-2 RE</b>	0 601 19B 403, 503				
<b>GSB 20-2 RE</b>	0 601 194 703, 708, 775, 790, 795				
<b>GWS 15-125 CI</b>	3 601 G95 000				
<b>GWS 15-125 CIE</b>	3 601 G96 000				
<b>GWS 15-125 CIEH</b>	3 601 H30 300, 320, D00				
<b>GWS 15-125 CIEP</b>	3 601 G96 200				
<b>GWS 15-125 CIEX</b>	3 601 G96 100				
<b>GWS 15-125 CIH</b>	3 601 H30 200, 220, C00				
<b>GWS 15-125 CIP</b>	3 601 G95 200				
<b>GWS 15-125 CIPX</b>	3 601 G95 300, 340				
<b>GWS 15-125 CIT</b>	3 601 G97 000				
<b>GWS 15-125 CITH</b>	3 601 H30 400, 420, 700, G00				
<b>GWS 15-125 CIX</b>	3 601 G95 100				
<b>GWS 15-125 Inox</b>	3 601 G9X 000				
<b>GWS 15-150 CI</b>	3 601 G98 000				
<b>GWS 15-150 CIH</b>	3 601 H30 500, 520				
<b>GWS 15-150 CIP</b>	3 601 G98 200				
<b>GWS 17-125 CIE</b>	3 601 G96 0R0				
<b>GWS 17-125 CIE</b>	3 601 G9H 000				
<b>GWS 17-125 CIEX</b>	3 601 G9H 100				
<b>GWS 17-125 CIT</b>	3 601 G97 0R0				
<b>GWS 17-125 CIT</b>	3 601 G9J 000				
<b>GWS 17-125 CIX</b>	3 601 G9G 100				
<b>GWS 17-125 INOX</b>	3 601 G9M 000				
<b>GWS 17-150 CI</b>	3 601 G98 0R0				
<b>GWS 17-150 CI</b>	3 601 G9K 000				
<b>GWS 19-125 CI</b>	3 601 G9N 000				
<b>GWS 19-125 CIE</b>	3 601 G9P 000				
<b>GWS 19-125 CIST</b>	3 601 G9S 000				
<b>GWS 19-150 CI</b>	3 601 G9R 000				
<b>GWS 19-180</b>	0 601 351 103, 108, 803				
<b>GWS 19-230</b>	0 601 352 103, 108, 803				
<b>GWS 20-180</b>	0 601 356 003, 903				
<b>GWS 20-180</b>	0 601 751 003, 008, 013, 020				
<b>GWS 20-180 H</b>	0 601 849 003				
<b>GWS 20-180 H</b>	3 601 H49 L03				
<b>GWS 20-180 J</b>	0 601 751 913				
<b>GWS 20-180 JH</b>	0 601 849 903				
<b>GWS 20-230</b>	0 601 752 003, 008, 013				
<b>GWS 20-230</b>	0 601 850 193				
<b>GWS 20-230 H</b>	0 601 850 003, 065, 103, 108				
<b>GWS 20-230 J</b>	0 601 752 903, 908, 913, 965				
<b>GWS 20-230 JH</b>	0 601 850 903, 908				
<b>GWS 20-230H</b>	3 601 H50 101, 102, L00, L01, L02				
<b>GWS 20-230JH</b>	3 601 H50 M00, M01				
<b>GWS 21-180</b>	0 601 356 103, 803				
<b>GWS 21-180 H</b>	0 601 851 003, 008, 083, 0A3, 0L4				
<b>GWS 21-180 H</b>	3 601 H51 L03				
<b>GWS 21-180 HV</b>	0 601 851 B03, B08				
<b>GWS 21-180 JH</b>	0 601 851 903, 908				
<b>GWS 21-180 JHV</b>	0 601 851 G03, G08, G18				
<b>GWS 21-230</b>	0 601 357 103, 188, 803				
<b>GWS 21-230 H</b>	0 601 852 003, 008, 083, 0A3				
<b>GWS 21-230 H</b>	3 601 H52 L02				
<b>GWS 21-230 HV</b>	0 601 852 B03, B08				
<b>GWS 21-230 JH</b>	0 601 852 903, 908				
<b>GWS 21-230 JHV</b>	0 601 852 G03, G08				
<b>GWS 22-180 H</b>	3 601 H81 100, 101, L00, L01, L02, Y00, Y01				
<b>GWS 22-180 JH</b>	3 601 H81 M00, M01, M02, Z00				

