



BOSCH

Разработано для жизни



1	2	3	4	5
1607031255	1607031250	1607031266	1607031256	1607031223

6	7	8	9	10
1607031227	1607031252	1607031260	1607031254	1607031236

11	12	13	14	15
1607031264	1607031265	1607031263	1607031259	1607031222

GWS 23-180	0 601 753 003	GWS 26-230 JH	3 601 H56 100, 101, 102, 1P1, 1P2, L41, L42, M00, M01, M02	GSR 8-6 KE	0 601 426 703	15
GWS 23-180 + SDS	0 601 753 173	GWS 26-230 LVI	3 601 H95 F00, F01, H00, H01	Гайковерт (GDS)		
GWS 23-180 J	0 601 753 873, 878, 903	GWS 580	0 601 376 003, 008	GDS 18 E	0 601 436 808, 803	15
GWS 23-180 JS	0 601 753 973	GWS 600	0 601 375 0VH	Рубанок (GHO)		
GWS 23-180 S	0 601 753 073	GWS 6-115	0 601 375 003, 008, 0V6, 0V7, 903, 908	GHO 31-82	0 601 593 003, 103, 166, 168	15
GWS 23-230	0 601 362 003, 903	GWS 6-115 E	0 601 375 503, 703, 708, 7A3, 7A8	Ударная дрель (PSB)		
GWS 23-230	0 601 754 003, 008, 173	GWS 660	0 601 375 065, 0V0	PSB 500 R	0 603 312 803, 808	15
GWS 23-230 J	0 601 754 903, 908	GWS 7-115	0 601 380 003, 073, 103, 903, 948	PSB 550 RE	0 603 169 703	
GWS 23-230 JS	0 601 754 973, 978	GWS 7-115	0 601 700 003, 008, 903, 908	PSB 550 RE	3 603 A26 001	
GWS 23-230 S	0 601 754 073, 873, 878	GWS 7-115	0 601 800 003	PSB 500	3 603 A26 000	
GWS 24-180	0 601 361 103, 803	GWS 7-115	0 601 800 003	PSB 530 RE	3 603 A26 002	
GWS 24-180 B	0 601 853 003	GWS 7-115	3 601 C88 101	PSB 530 RA	3 603 A26 100	11
GWS 24-180 H	0 601 853 403, 493, 100	GWS 7-115	3 601 C88 102	PSB 650 RE	3 603 A26 200	
GWS 24-180 JB	0 601 853 903	GWS 7-115	3 601 C88 101	PSB 600 RE	3 603 A26 201, 400	
GWS 24-180 JBV	0 601 853 G03, G08	GWS 7-115	3 601 C88 102	PSB 650 RA	3 603 C85 703	
GWS 24-180 JBX	0 601 863 873	GWS 7-115	3 601 C88 102	PSB 550 RA	3 603 C97 400, 402	
GWS 24-180 JH	3 601 H53 M00	GWS 7-115	3 601 C88 101	Рубанок (PHO)		
GWS 24-180 JH	3 601 H83 101, M00, M01	GWS 7-115	3 601 C88 102	PHO 1	0 603 272 203, 208	15
GWS 24-180 LVI	3 601 H92 F00, F01	GWS 7-115	3 601 C88 102	PHO 15	0 603 997 989	
GWS 24-230	0 601 362 103, 178, 803, 878	GWS 7-115	3 601 C88 101	PHO 15-82	0 603 272 103, 160	
GWS 24-230 B	0 601 854 003, 008	GWS 7-115	3 601 C88 102	PHO 20-82	0 603 258 403	
GWS 24-230 BV	0 601 854 B03, B08	GWS 7-115	3 601 C88 101	PHO 25-82	0 603 296 003	
GWS 24-230 H	0 601 854 403, 408, 493	GWS 7-115	3 601 C88 102	PHO 25-83	0 603 296 008	
GWS 24-230 H	3 601 H54 100, L00	GWS 7-115	3 601 C88 101	PHO 25-91	0 603 296 063	
GWS 24-230 H	3 601 H84 L00, L01	GWS 7-115	3 601 C88 102	Ленточная шлифмашина (PBS)		
GWS 24-230 JB	0 601 854 878, 903, 908	GWS 7-115	3 601 C88 101	PBS 75 A	0 603 270 203	15
GWS 24-230 JBV	0 601 854 G03, G08	GWS 7-115	3 601 C88 102	PBS 75 AE	0 603 270 503, 508, 603	
GWS 24-230 JBX	0 601 864 873	GWS 7-115	3 601 C88 101	PBS 7 A	0 603 391 003, 008, 080	
GWS 24-230 JBX	3 601 H64 400, R00, T00	GWS 7-115	3 601 C88 102	PBS 7 AE	0 603 391 760, 768	11
GWS 24-230 JH	0 601 854 503	GWS 7-115	3 601 C88 101	PBS 7 A/AE	0 603 391 780	
GWS 24-230 JH	3 601 H54 M00	GWS 7-115	3 601 C88 102	Эксцентриковая шлифмашина (PEX)		
GWS 24-230 JH	3 601 H84 201, 204	GWS 7-115	3 601 C88 101	PEX 11 A	0 603 309 003	15
GWS 24-230 JVX	3 601 H64 500, 501, 502, 505, U00, U07, Z00, Z01, Z02, Z05	GWS 7-115	3 601 C88 102	PEX 125 A-1	0 603 283 103, 203, 208	
GWS 24-230 LVI	3 601 H93 F00, F01, H00, H01	GWS 7-115	3 601 C88 101	PEX 125 A-2	0 603 283 503	
GWS 24-230JVX	3 601 H64 U01	GWS 7-115	3 601 C88 102	PEX 125 AE-1	0 603 283 603	
GWS 24-300	0 601 364 003	GWS 7-115	3 601 C88 101	PEX 220 A	3 603 C78 000, 001	11
GWS 24-300 I	0 601 364 903, 973	GWS 7-115	3 601 C88 102	Вибрационная шлифмашина (PSS)		
GWS 24-300I	3 601 C64 801	GWS 7-115	3 601 C88 101	PSS 28 AE	0 603 285 703	15
GWS 25-180	0 601 755 003, 008, 173	GWS 7-115	3 601 C88 102	PSS 200 A	3 603 C40 000, 001	
GWS 25-180 J	0 601 755 873, 903	GWS 7-115	3 601 C88 101	PSS 200 AC	3 603 C40 100, 102	
GWS 25-180 JS	0 601 755 973	GWS 7-115	3 601 C88 102	PSS 190 AC	3 603 C40 101, 103	11
GWS 25-180 S	0 601 755 073	GWS 7-115	3 601 C88 101	PSS 250 AE	3 603 C40 200	
GWS 25-230	0 601 756 003, 008, 173	GWS 7-115	3 601 C88 102	PSS 300 AE	3 603 C40 300	
GWS 25-230 J	0 601 756 873, 878, 903	GWS 7-115	3 601 C88 101	PSS 280 A	3 603 C40 600	
GWS 25-230 JS	0 601 756 973, 978	GWS 7-115	3 601 C88 102	Лобзик (PST)		
GWS 25-230 S	0 601 756 073	GWS 7-115	3 601 C88 101	PST 700 PAE	0 603 303 603, 608, 680	15
GWS 26-180 B	0 601 855 003	GWS 7-115	3 601 C88 102	PST 800 PAC	0 603 303 703, 708	
GWS 26-180 BV	0 601 855 B03	GWS 7-115	3 601 C88 101	PST 700 PE	3 603 C51 100	
GWS 26-180 H	0 601 855 403, 493	GWS 7-115	3 601 C88 102	PST 700 PE	3 603 D13 400	
GWS 26-180 H	3 601 H55 100	GWS 7-115	3 601 C88 101	PST 800 PEL	3 603 C52 100	
GWS 26-180 JB	0 601 855 903	GWS 7-115	3 601 C88 102	PST 800 PEL	3 603 CA0 100, 101	
GWS 26-180 JBV	0 601 855 G03	GWS 7-115	3 601 C88 101	PST 900 PEL	3 603 C53 100	
GWS 26-180 JBV	3 601 H55 U00	GWS 7-115	3 601 C88 102	PST 900 PEL	3 603 CA0 200	
GWS 26-180 JH	3 601 H55 101, 102, M00, M01	GWS 7-115	3 601 C88 101	PST 650	3 603 CA0 200	
GWS 26-180 LVI	3 601 H94 F00, F01	GWS 7-115	3 601 C88 102	PST 650	3 603 CA0 700	
GWS 26-230 B	0 601 856 003	GWS 7-115	3 601 C88 101	PST 650	3 603 D13 000	
GWS 26-230 B	3 601 H56 300, 301, 302	GWS 7-115	3 601 C88 102	PST 600	3 603 C92 020	
GWS 26-230 BV	0 601 856 B03	GWS 7-115	3 601 C88 101	PST 680 E	3 603 C92 100	11
GWS 26-230 H	0 601 856 403, 493	GWS 7-115	3 601 C88 102	PST 650 L	3 603 C92 200	
GWS 26-230 JB	0 601 856 903, 908	GWS 7-115	3 601 C88 101	PST 680 EL	3 603 C92 300	
GWS 26-230 JBV	0 601 856 G03, G08	GWS 7-115	3 601 C88 102	PST 700 E	3 603 CA0 000	
GWS 26-230 JBV	3 601 H56 500, S00, U00	GWS 7-115	3 601 C88 101	PST 7000 E	3 603 CA0 001	
GWS 26-230 JH	0 601 856 503	GWS 7-115	3 601 C88 102	PST 1000 PEL	3 603 CA0 300	
		GWS 7-115	3 601 C88 101	PST 750 PE	3 603 CA0 301, 500, 501, 502	
		GWS 7-115	3 601 C88 102	PST 750 PEL	3 603 CA0 600, 601	
		GWS 7-115	3 601 C88 101	PST 670 L	3 603 D13 100	
		GWS 7-115	3 601 C88 102	PST 700 PEL	3 603 D13 500	